

**IN THE UNITED STATES PATENT & TRADEMARK OFFICE**

ATTORNEY DOCKET NUMBER: 10003439-I

IN RE APPLICATION OF: U.S. Patent No. 7,068,073

USPTO CONFIRMATION CODE: 6675

APPLICATION NO.: 09/811,192

FILED: Mar. 17, 2001

EXAMINER: James H. Cho

GROUP ART UNIT: 2819

FOR: CIRCUIT FOR SWITCHING ONE OR MORE HVD TRANSCEIVERS

**37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION**

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 09/811,192, now Patent Number 7,068,073.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

All errors were the fault of the USPTO, no fee required. In the event that a further fee is required, please charge the amount to Deposit Account No. 082025.

All errors were the fault of the applicant and, accordingly, please charge **\$100.00** to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The errors were the fault of both the applicant and USPTO and, accordingly, please charge **\$100.00** to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

On the face page, in field (56), under "Foreign Patent Documents", in column 2, line 1, delete "DE" and insert -- EP --, therefor.  
(List of references cited by examiner dated Jul. 14, 2004, page 1 of 1, under "Foreign Patent Documents", entry 1)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

3-APR-2009  
DATE

*michael czarnecki* Reg. No. 61,257  
Name: Michael S. Czarnecki  
Registration No.: 61,257

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY  
Intellectual Property Administration  
P.O. Box 272400  
Fort Collins, Colorado 80527-2400